

Stan of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date: September 26, 2006

Supervisor

Mine Name: Red Sandstone Quarry

Operator Name: Ron Stout

900 Industrial Road

P.O. Box 251

St. George, Utah 84770

Inspector(s): Doug Jensen Other Participants: None Mine Status: Active

Weather:	Clear,	hot
----------	--------	-----

Time: 5:15 PM

Permit number: S/05**2**/073

Date: September 12, 2006

Elements of Inspection		Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds				
2. Public Safety (shafts, adits, trash, signs,	highwalls)			
3. Protection of Drainages / Erosion Control	ol			
4. Deleterious Material				
5. Roads (maintenance, surfacing, dust cor	trol, safety)			
6. Concurrent Reclamation				
7. Backfilling/Grading (trenches, pits, road	ds,			
highwalls, shafts, drill holes)				
8. Water Impoundments				
9. Soils				
10. Revegetation				
11. Air Quality				
12. Other				

Purpose of Inspection:

The operator requested that the Division inspect and close this permit.

Directions to Site:

See previous inspection report.

Inspection Summary:

The operator has requested a release of the permit due to the fact that this site is located in an industrial area that is being developed. Mr. Stout has stated that he is developing his site with the same purpose as the adjacent landowners. There is an adjacent area to this quarry that is being developed much the same as the Red Sandstone permit area. With the growth of St. George industrial land is at a premium and when the rock removal is completed, Mr. Stout's property will become an additional part of this area.

Conclusions and Recommendations:

All the land involved in and around the quarry is a part of an industrial area. The area to the north is a tortoise reserve and cannot be developed. The areas to the west of the site are being similarly developed for the purpose of expanding the industrial area. Material removal has already occurred east of the site and industrial buildings have been constructed.

S/053/0073 Inspection Date: September 12, 2006; Report Date: September 26, 2006 Page 2 of 2

Mr. Stout has filed a map with the Division showing the ultimate development of this property. I believe that the map along with the development of the area around of the property is sufficient evidence to bear out Mr. Stout's contention that this property's post mining land use is such that reclamation will not be necessary.

Although no reclamation will be necessary, a discussion will need to take place as to whether the site needs to continue to be permitted by the Division.

A letter informing the operator of this decision will be written at a later date.

Inspector's Signature Long

M

Jensen Date: 9/26/06

dj:pb

cc:

Ron Stout

John Blake, SITLA ML-48974-MP

O:\M053-Washington\S0530073-RedSandstone\Inspections\09122006insp.doc